


Understanding **XRF** *Spectrometry*

A practical guide
with worked
examples

James P. Willis
Andrew R. Duncan



Volume
Basic concepts
and
instrumentation

Table of Contents

Foreword

F.1	INTRODUCTION.....	F-1
F.2	ACKNOWLEDGEMENTS	F-2
F.3	BIBLIOGRAPHY.....	F-3
F.4	SYMBOLS AND TERMINOLOGY.....	F-4
F.4.1	Symbols	F-4
F.4.2	Influence Coefficients	F-6
F.4.2.1	In the Rousseau algorithm	F-6
F.4.2.2	In the Lachance-Traill algorithm.....	F-6

Chapter 1: Properties of X-rays and X-ray spectra

1.1	X-RAYS	1-1
1.1.1	Properties of X-rays	1-1
1.1.2	Units of measurement.....	1-2
1.1.2.1	Wavelength (λ)	1-2
1.1.2.2	Energy (E) of an X-ray photon.....	1-2
1.1.2.3	Intensity (I or R)	1-3
1.2	X-RAY FLUORESCENCE SPECTROMETRY (XRFS)	1-3
1.3	INTERACTION OF X-RAYS WITH MATTER.....	1-3
1.4	X-RAY SPECTRA.....	1-4
1.4.1	Continuous spectrum or continuum	1-4
1.4.2	Characteristic line spectrum	1-4
1.4.2.1	Relative intensities of X-ray lines	1-6
1.4.3	Moseley's law	1-9
1.5	REFERENCES	1-11

Chapter 2: X-ray spectrometers; dispersion of X-rays

2.1	SPECTROMETERS	2-1
2.1.1	Different types of spectrometer	2-1
2.2	WAVELENGTH DISPERSIVE SPECTROMETERS	2-2
2.2.1	Bragg's law	2-3
2.2.2	Explanation of high (second, third and fourth) order reflections	2-4
2.2.2.1	Higher order reflections.....	2-4
2.2.3	Spectrometers	2-5
2.2.4	Collimators	2-6
2.2.5	Analysing crystals.....	2-8
2.2.5.1	Abnormal reflections	2-11
2.2.6	Orders of reflection	2-12
2.2.7	Angular resolution ($d\theta/d\lambda$)	2-14
2.2.8	Resolution	2-14
2.2.9	Sensitivity	2-15
2.2.10	Crystal fluorescence.....	2-15
2.2.11	X-ray detectors	2-15
2.2.12	Radiation path.....	2-16
2.2.13	Efficiency of spectrometers	2-16
2.3	REFERENCE	2-16

Chapter 3: Production of X-Rays

3.1	X-RAY TUBES	3-1
3.2	ORIGIN OF CONTINUOUS SPECTRUM	3-1
3.2.1	Short wavelength limit and shape of continuum	3-3
3.2.2	Effect of tube target material, tube voltage and tube current	3-3
3.3	ORIGIN OF CHARACTERISTIC X-RAY LINES	3-4
3.3.1	Diagram lines.....	3-4
3.3.2.	Excitation potential	3-9
3.3.3	K β (K-M _{2,3} , K-N _{2,3}) lines.....	3-9
3.3.4	Non-diagram/satelite lines	3-9
3.4	EXCITATION OF CHARACTERISTIC LINE SPECTRA	3-11
3.4.1	Primary excitation by electrons in X-ray tube.....	3-12
3.4.2	Primary tube spectrum	3-14
3.5	SECONDARY EXCITATION (IN THE SAMPLE) BY X-RAYS	3-15
3.5.1	Absorption edges.....	3-16
3.5.2	Secondary excitation by monochromatic X-rays	3-16
3.5.3	Secondary excitation by polychromatic X-rays	3-18
3.6	FLUORESCENT YIELD (ω).....	3-19
3.7	REFERENCES	3-24
3.8	AN EXERCISE IN THE USE OF KRAMERS' EQUATION	3-24

Chapter 4: Detection of X-Rays

4.1	INTRODUCTION.....	4-1
4.2	X-RAY DETECTORS	4-1
4.3	GAS-FLOW PROPORTIONAL DETECTOR ("FLOW COUNTER")	4-2
4.3.1	Basic structure of the flow counter	4-2
4.3.2	Flow counter window materials.....	4-3
4.3.2.1	Practical tip	4-4
4.3.3	The processes in the counter gas	4-4
4.3.4	Quenching	4-7
4.4	PULSE HEIGHT DISTRIBUTIONS AND DETECTOR RESOLUTION	4-7
4.4.1	Proportionality	4-7
4.4.2	Pulse height distribution	4-7
4.4.3	Detector resolution	4-9
4.5	SCINTILLATION DETECTOR	4-10
4.6	SEALED GAS DETECTORS	4-11
4.7	Si(Li) SEMICONDUCTOR DETECTOR	4-11
4.8	DETECTOR CHOICE IN WAVELENGTH-DISPERSIVE XRF SPECTROMETERS	4-14
4.9	THE DEAD TIME PHENOMENON	4-16
4.10	REFERENCES	4-18

Chapter 5: Pulse Height Distributions and Pulse Height Selection

5.1	INTRODUCTION.....	5-1
5.2	PULSE HEIGHT DISTRIBUTION	5-1
5.3	FORMATION OF ESCAPE PEAKS IN A PULSE HEIGHT DISTRIBUTION	5-2
5.3.1	Escape peak formation in a gas-filled detector	5-3
5.3.2	Escape peak formation in a scintillation detector	5-5
5.3.3	Escape peak formation in a Si(Li) semiconductor detector	5-7
5.4	COUNTING CHAIN ELECTRONICS AND THE PULSE HEIGHT SELECTOR	5-8
5.5	PULSE HEIGHT DISTRIBUTION PLOTS AND WAVELENGTH SCANS	5-9
5.6	OPERATION OF A PULSE HEIGHT SELECTOR.....	5-10
5.7	FACTORS CONTROLLING PULSE HEIGHT AND WIDTH	5-12

5.8	APPLICATIONS OF PULSE HEIGHT SELECTION	5-13
5.8.1	Elimination of higher-order spectral line interference	5-13
5.8.2	Reduction of background intensity	5-14
5.8.3	Minimise interference due to crystal fluorescence.....	5-15
5.8.4	Non-dispersive XRF analysis.....	5-17
5.9	AUTOMATIC PULSE HEIGHT SELECTION.....	5-18
5.10	PROBLEMS ARISING IN PULSE HEIGHT SELECTION.....	5-19
5.10.1	Pulse height shifts	5-19
5.10.2	Pulse amplitude distortions	5-21
5.11	SETTING THE PULSE HEIGHT SELECTOR.....	5-23
5.12	SOME USEFUL HINTS	5-23
5.12.1	Alignment of analysing crystals using high order lines.....	5-23
5.12.2	Adjustment of $\sin\theta$ amplifier	5-24
5.13	REFERENCES	5-24

Chapter 6: Energy Dispersive XRF Spectrometry

6.1	INTRODUCTION.....	6-1
6.2	COMPONENTS OF AN EDXRF SYSTEM	6-4
6.2.1	Semi-conductor Detector	6-4
6.2.2	Amplifier	6-6
6.2.3	Pulse pileup rejector	6-7
6.2.4	Multichannel analyser.....	6-10
6.3	METHODS OF EXCITATION	6-10
6.3.1	X-ray Tubes	6-10
6.3.2	Radioisotope Excitation	6-12
6.4	SUMMARY OF EDXRF	6-13
6.4.1	Key Issues.....	6-13
6.4.2	Pros and Cons	6-14
6.5	PREFERRED APPLICATION AREAS FOR EDXRF SPECTROMETRY	6-14
6.6	REFERENCES	6-14

Chapter 7: Scattering of X-rays

7.1	SCATTERING OF X-RAYS	7-1
7.1.1	Source of scattered background.....	7-1
7.1.2	Coherent or Rayleigh scattering	7-1
7.1.3	Incoherent or Compton scattering.....	7-2
7.1.3.1	Explanation for broadening of Compton peaks	7-4
7.1.3.2	Compton peak intensity.....	7-5
7.1.3.3	Use of Compton peaks	7-6
7.1.4	Compton scattering of sample spectral lines	7-7
7.2	REFERENCES	7-8

Chapter 8: Matrix Effects: Absorption

8.1	ELEMENTAL AND PHYSICAL EFFECTS.....	8-1
8.2	ABSORPTION	8-1
8.2.1	Mass attenuation coefficient.....	8-2
8.2.2	Detailed explanation of total absorption	8-3
8.3	USE OF MASS ATTENUATION COEFFICIENTS	8-5
8.4	CALCULATION OF MASS ATTENUATION COEFFICIENT	8-5
8.4.1	Calculation of "total or effective" mass attenuation coefficient.....	8-6
8.5	RELATION BETWEEN INTENSITY AND MASS ATTENUATION COEFFICIENT	8-8
8.6	REFERENCES	8-10

Chapter 9: Matrix Effects: Enhancement; Particle Size; Chemical Effects. Infinite Thickness

9.1	ENHANCEMENT	9-1
9.2	PARTICLE SIZE EFFECTS.....	9-2
9.2.1	An aid to understanding particle size effects	9-6
9.3	CHEMICAL EFFECTS	9-9
9.4	INFINITE THICKNESS.....	9-10
9.5	REFERENCES	9-14

Chapter 10: Introduction to Quantitative Analysis

10.1	INTRODUCTION.....	10-1
10.2	BASIC COUNTING STATISTICS	10-2
10.2.1	Introduction.....	10-2
10.2.2	Statistical terms	10-2
10.2.3	Quantitative analysis.....	10-3
10.2.4	Errors	10-4
10.2.5	Gaussian distribution	10-4
10.2.6	Standard deviation of total counts (s_N)	10-6
10.2.7	Coefficient of Variation (COV) of total counts	10-6
10.2.8	Standard deviation of count rate (s_i)	10-7
10.2.9	Counting error of net intensity.....	10-8
10.2.9.1	Fixed Time	10-10
10.2.9.2	Fixed Count	10-10
10.2.10	Lower limits of detection.....	10-10
10.2.11	Figure of Merit (FOM)	10-10
10.2.12	Errors in XRFS analysis.....	10-11
10.3	CALIBRATION EQUATIONS, LINES AND PLOTS	10-11
10.3.1	First order polynomial equations.....	10-13
10.3.1.1	Using net peak intensities - no intercept	10-13
10.3.1.2	Using gross peak intensities - with intercept.....	10-14
10.3.2	Second order polynomial equations.....	10-15
10.3.3	Third and higher order polynomial equations	10-15
10.4	LIMITATIONS ON USE OF CALIBRATION LINES/EQUATIONS.....	10-15
10.5	CALIBRATION PROCEDURES INCORPORATING "MATRIX CORRECTION"	10-16
10.5.1	Calibration when $M_{i,s} \approx M_{i,st}$	10-17
10.5.2	Calibration when $M_{i,s}$ unequal to $M_{i,st}$	10-17
10.5.2.1	Use of Mass Attenuation Coefficients (MACs)	10-18
10.5.2.2	Use of Influence Coefficients and Fundamental Parameters	10-18
10.6	LIMITATIONS OF MAC AND INFLUENCE COEFFICIENT EQUATIONS	10-20
10.7	REFERENCES	10-21

Chapter 11: Sampling and Specimen Preparation

11.1	INTRODUCTION.....	11-1
11.2	SAMPLING METHODS	11-2
11.3	SIZE OF ORIGINAL SAMPLE	11-4
11.4	CRUSHING AND GRINDING.....	11-4
11.5	SIEVING.....	11-6
11.6	SAMPLE PREPARATION TECHNIQUES	11-6
11.6.1	Powders	11-6
11.6.1.1	Binders	11-9
11.6.2	Dilution	11-10
11.6.3	Fusions	11-10
11.6.3.1	Possible fluxes	11-10
11.6.3.2	Crucibles	11-10

11.6.3.3	Fusion temperatures	11-10
11.6.3.4	Addition of an oxidising agent	11-10
11.6.3.5	Problems of fusions	11-10
11.6.3.6	Annealing	11-11
11.6.3.7	Uptake of moisture and carbon dioxide.....	11-11
11.6.3.8	Example of loss of alkali elements during preparation of fusion disks	11-11
11.7	METALS	11-14
11.7.1	Surface Preparation	11-14
11.7.2	Surface Preparation Equipment.....	11-14
11.7.3	Remelting	11-15
11.7.4	Sample preparation equipment for metals	11-15
11.7	REFERENCES	11-15

Chapter 12: Selection of Instrumental Parameters

12.1	INTRODUCTION.....	12-1
12.2	CHOICE OF SPECTROMETER.....	12-1
12.3	TUBE TARGET SELECTION.....	12-2
12.4	TUBE VOLTAGE SELECTION	12-4
12.5	TUBE (PRIMARY BEAM) FILTER	12-4
12.6	COLLIMATOR MASK.....	12-6
12.7	PRIMARY COLLIMATOR	12-8
12.8	ANALYSING CRYSTALS	12-9
12.8.1	Crystal Fluorescence	12-13
12.9	SECONDARY OR AUXILIARY COLLIMATORS	12-13
12.10	SPECTROMETER MEDIUM.....	12-13
12.11	X-RAY DETECTORS	12-15
12.12	PULSE HEIGHT SELECTION	12-18
12.13	COUNTING TIME.....	12-20
12.14	FIGURE OF MERIT.....	12-21
12.15	PARAMETER SELECTION	12-21

Summary and Conclusion

S.1	SUMMARY.....	S-1
S.2	SETTING UP AN ANALYTICAL PROGRAM	S-9
S.3	CONCLUSION	S-13

X-ray Tables

T.1	COPYRIGHT PERMISSIONS	T-1
T.2	REFERENCES	T-1
Periodic Table for XRFS.....		T-3
Table 1.	Wavelengths of the principal K X-ray spectral lines (Å).....	T-4
Table 1a.	Wavelengths of the principal K X-ray spectral lines (nm)	T-6
Table 2.	Wavelengths of the principal L X-ray spectral lines (Å)	T-8
Table 2a.	Wavelengths of the principal L X-ray spectral lines (nm).....	T-10
Table 3.	Wavelengths of the principal M X-ray spectral lines (Å)	T-12
Table 3a.	Wavelengths of the principal M X-ray spectral lines (nm).....	T-14
Table 4.	Photon energies of the principal K and L Series X-ray spectral lines	T-16
Table 4a.	Photon energies of the principal M Series X-ray spectral lines	T-18
Table 5.	Wavelengths of the K, L and M X-ray Absorption Edges (Å).....	T-20
Table 5a.	Wavelengths of the K, L and M X-ray Absorption Edges (nm)	T-22
Table 6.	K, L and M X-ray Excitation Potentials and Binding Energies.....	T-24
Table 7-1.	Parameters used in Leroux and	
	Thin equations: $\mu = C \cdot E_{ab} \cdot \lambda^n = C \cdot E_{ab} \cdot (12.3981/E)^n \text{ cm}^2 \cdot \text{g}^{-1}$	T-26
Table 7-2.	MACs for various wavelengths ($\lambda = 0.31 - 6.0 \text{ \AA}$)	T-28

Table 7-3.	MACs for K α lines of elements Z = 11 - 20 (Na - Nd).....	T-31
Table 7-4.	MACs for L α_1 lines of elements Z = 30 - 40 (Zn - Pu).....	T-36
Table 7-5.	MACs for L β_1 lines of elements Z = 30 - 40 (Zn - Pu).....	T-42
Table 8.	K and L _{III} Absorption Edge Jump Ratios (r) and (r - 1)/r values.....	T-48
Table 9.	Average K, L and M Fluorescence Yields for elements Z = 4-94	T-49
Table 10.	Relative K and some L Line Intensities within a Series (f _X)	T-50
Table 11.	Some Useful "Oxide to Element" and "Element to Oxide" conversion factors (gravimetric factors)	T-52
Table 12.	International Atomic Weights	T-53
Table 13.	Correspondence between Siegbahn and IUPAC notation for X-ray diagram lines	T-54

Index